

Oil Field Environmental Incident Summary

Incident: 20150420150614 **Date/Time of Notice:** 04/20/2015 15:06

Responsible Party: ENCORE ENERGY PARTNERS OPERATING LLC

Well Operator: ENCORE ENERGY PARTNERS OPERATING LLC

Well Name: MARTIN-FEDERAL 15-1

Field Name: TRENTON

Well File #: 11721

Date Incident: 4/20/2015

Time Incident: 10:00

Facility ID Number:

County: WILLIAMS

Twp: 153

Rng: 102

Sec: 15

Qtr: NW SW

Location Description: Tank Berm for Martin Federal 15-1

Submitted By: Bart Brinkerhoff

Received By:

Contact Person: Bart Brinkerhoff
Box 569
powell, , wy 82435

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	Barrels	20	Barrels	20	barrels

Brine

Other

Description of Other Released Contaminant:

Oil only.

Inspected:

Written Report Received: 12/3/2015

Clean Up Concluded: 5/4/2015

Risk Evaluation:

Vacuum trucks have vacuumed up the oil. washing with fresh water.

Areal Extent:

Potential Environmental Impacts:

none. any oil and wash water will be vacuumed up and recycled.

Action Taken or Planned:

Crews are unplugging the equalizer line. The spill stayed in the tank berm.

Wastes Disposal Location: All fluids recycled on the well site.

Agencies Involved:

Updates

Date: 4/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained within the dikes on location. NDIC retains oversight.